

Oil Field Environmental Incident Summary

Incident: 20150226090048 **Date/Time of Notice:** 02/26/2015 09:00

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: LK-A QTR CIR- 147-96-1807H-5

Field Name: BIG GULCH

Well File #: 28586

Date Incident: 2/25/2015

Time Incident: 01:30

Facility ID Number:

County: DUNN

Twp: 147

Rng: 96

Sec: 18

Qtr:

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16th Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	18	Barrels	17.5	Barrels	17.5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/28/2015

Clean Up Concluded: 4/2/2015

Risk Evaluation:

The source of the release was secured immediately upon discovery of the incident. The released produced water remained on the location.

Areal Extent:

N/A - the release remained on the location.

Potential Environmental Impacts:

Approximately 18 bbls of produced water was released into a secondary containment berm, and approximately 10 gallons migrated outside of the secondary containment berm. The released produced water remained on the location, and a vacuum truck was utilized to recover as much of the

Action Taken or Planned:

A vacuum truck was utilized to recover as much of the released produced water as practicable. The affected area outside of the secondary containment berm will be further evaluated for impacts.

Wastes Disposal Location: A properly permitted disposal facility.

Agencies Involved:

Updates

Date: 2/27/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to pump leak, remained on location according to the report. NDIC retains oversight.